



NOTES:

1. See Additional Pavement Repair and Mill and Overlay Notes on Details 119, 121, and 123 as Appropriate.
2. In Addition to the Noted Minimum Mill and Overlay Limits on This Detail, the Town Will Further Identify Any Additional or Decreased Limits Based on Actual Field Conditions, Such as Multiple Repair Areas, Paver Fields, Existing Pavement Patch Areas, or Similar Field Conditions.
3. Refer to Details 112a, 112b, 112c, 112d, and 113 for Additional Mill and Overlay Requirements and Pavement Specifications.



TOWN OF JUPITER
ENGINEERING DIVISION
 210 MILITARY TRAIL
 JUPITER, FLORIDA 33458
 (561) 746-5134

Pavement Damage Repair
Detail & Specifications
 V:\Engineering\Drawings\Details\2026\119a - PavementDamageRepair.dwg

DETAIL NUMBER
119a
 Revised 202511